Marmon Link Product Management
8800 95th Avenue North
Brooklyn Park, MN 55443 USA
Telephone 763.488.3010

Facsimile 1.866.329.6392
E-mail: CXTEAM@marmonfoodservice.com

Marmon Link Product Advisory

Subject: Part Number 620067479 Transformer 115 240V 60Hz 16-32V Pre-Wired
Advisory No: Product Advisory No. 093026A
Date: 30 September 2026

Dear Valued Customer:
Our records indicate that you have recently purchased and/or ordered part number:

Manufacturer Part Number: 620067479
Description: Transformer 115 240V 60Hz 16-32V Pre-Wired

Marmon Foodservice Technologies has been notified that **part number 620067479 is now obsolete and is no longer available for purchase**.

This discontinuation occurred without advance notice from the supplier, and unfortunately, no opportunity was provided to place a last-time buy.

Customers should begin ordering **part number 620075777** as the approved replacement for part number 620067479.

Ordering Information

- **Do not place new orders for:** 620067479
- **Order replacement part:** 620075777
- Please update any internal ordering systems, service documentation, stocking lists, and preventive maintenance materials that reference the obsolete part number.

Marmon Link Product Management
8800 95th Avenue North
Brooklyn Park, MN 55443 USA
Telephone 763.488.3010

Facsimile 1.866.329.6392
E-mail: CXTEAM@marmonfoodservice.com

Marmon Foodservice Technologies understands that unexpected product obsolescence can affect inventory planning and service operations. We apologize for any inconvenience this change may cause and appreciate your understanding as we transition to the replacement part.

For questions regarding this advisory, part availability, or existing orders, please contact your **Marmon Foodservice Technologies Customer Service representative**.

Your Customer Care representative can be reached at CXTEAM@marmonfoodservice.com or 866-275-6392.

Thank you,
Marmon Link Product Management